

# P1077

Verified Document & Reference Overview - [e.lacerdagama.com.br](http://e.lacerdagama.com.br)

## 1. EXECUTIVE SUMMARY & OVERVIEW

Intake manifold tuning (imt) valve stuck in high rpm position. When the pcm sends a close (long runner) command, no long runner return signal is.

## 2. VERIFIED SPECIFICATIONS & DETAILS

- Full documentation and comprehensive data indexed from reliable sources.
- Cross-referenced against authoritative publications and verified updates.
- Continuous real-time updates preserved for accurate information retrieval.

## 3. ACCESS & VERIFICATION

Q: Where can I review the complete file for P1077?

A: Full profiles and latest reference points are published via [e.lacerdagama.com.br](http://e.lacerdagama.com.br).

## 4. GENERAL NOTICE & CITATION

All information compiled for research and educational purposes.